

Ms. Sheri Bianchin
May 5, 2017
Page 2

The locations of the 17 remediated residential properties (in relationship to the Taracorp pile) are shown on Figure 1. Photographs showing the remediated and restored areas on the 17 properties are attached. Notes regarding two properties follow:

- On the **non-responsive** property and as shown on the photographs, the property owner has removed soil/grass on the front side of the property along Bryan Avenue. No remedial activities were required in the area where the property owner removed the soil/grass.
- On the **non-responsive** property, excavated areas were restored with approved topsoil. Due to the presence of debris, tree shading, etc. on the property, the property owner requested that no sod be placed into the excavated areas.

Based upon the final inspection, the Group believes that it has satisfactorily completed the work associated with the 2016 residential soil remediation. EWI is currently preparing a report on the Group's behalf to document the remedial activities performed in 2015 and 2016.

Please let me know if you have questions.

Very truly yours,

LEED ENVIRONMENTAL, INC.



Jeffrey A. Leed
Project Coordinator

attachments


cc: Ms. Erin Rednour – Illinois EPA (w/attachments, by electronic mail)
Mr. Tom Miller – Illinois EPA (w/attachments, by electronic mail)
Mr. Dan Zahner – Environmental Works, Inc. (w/attachments, by electronic mail)
Technical Committee, NL Industries/Taracorp Superfund Site Group
(w/attachments, by electronic mail)





non-responsive, Granite City





non-responsive, Granite City





non-responsive, Granite City







non-responsive, Madison







non-responsive , Madison



non-responsive, Madison



non-responsive, Madison





non-responsive, Granite City





non-responsive, Madison









non-responsive, Granite City





non-responsive, Granite City



non-responsive, Madison



non-responsive, Madison

